

STATUS OF J-PARC ACCELERATOR FACILITIES AFTER THE GREAT EAST JAPAN EARTHQUAKE

K. Hasegawa[#], M. Kinsho, H. Oguri, J-PARC/JAEA, Tokai, Japan
 T. Koseki, J-PARC/KEK, Tokai, Japan

Abstract

J-PARC was severely affected by the March 11 Great East Japan Earthquake. When the earthquake struck, we had a beam study operation of the linac, and the machine automatically stopped immediately. Many places particularly around buildings subsided. Underground water came into the linac and the main ring tunnels as well. The water level at the linac reached a depth of 10 cm, but pumping out flooding water with using a diesel generator was succeeded lowering the water level. At the Rapid Cycling Synchrotron (RCS), the surrounding road got wavy, and the yard area for electricity and cooling water devices was severely distorted. We investigated damages of each facility, and have been trying to restore the facilities.

INTRODUCTION

J-PARC, which stands for Japan Proton Accelerator Research Complex, consists of a linac, a 3 GeV synchrotron (RCS) and a Main Ring synchrotron (MR) and a few experimental facilities. A proton beam from the RCS is injected to the Materials and Life Science Experimental Facility (MLF) for neutron and muon experiments. The MR accelerates a beam up to 30 GeV. The beam is used for hadron or neutrino experiments.

No user services were coincidentally scheduled in the daytime of March 11. Beam study at the linac, and radiation survey work at the RCS and MR tunnels were carried out, respectively. The earthquake occurred when we suspended a beam for changing a beam destination from the linac to the RCS. The earthquake intensity was 6 lower at Tokai on the Japanese seismic scale of zero to seven. It is extremely fortunate that we had no effects from tsunami and no one was injured.

STATUS OF LINAC

The linac building is approximately 330 m in length, and 44-48 m in width. A wide area at the entrance of the linac building subsided ~1.5 m, and almost all water supply and drainage pipes were broken as shown in Fig. 1.

We could not get into the building until March 17 due to many strong aftershocks after the earthquake. It was found that there were no severe damages on the accelerator itself, but that water accumulated 1 cm in deep on a floor of the linac tunnel. When we entered the tunnel again a week later on 24th the water level increased to approximately 10 cm as shown in Fig. 2. It meant the water level increased more than 1 cm per day, and then we decided to pump it out immediately. Since the electricity

had yet not been restored for the building, we used a diesel engine generator. It took two days to drain approximately 150 m³ of water. When the floor exposed, a large number of lateral cracks were recognized on the floor and the walls mainly in the middle of the tunnel.



Figure 1: Subsidence at the entrance of the linac building.

We were afraid if any component of the linac was damaged by inundation. One of the components was a vacuum pump placed on the floor. We rinsed and dried the pumps, and then turned them on after checking insulation resistance. It turned out that eight pumps and four controllers out of 36 pumps were broken down. Small aluminium boxes for diagnostics pre-amplifiers on the floor had been also submerged, and resulted in being corroded by strong alkali water through the concrete wall. Several beam monitors and bellows welded to beam transport pipes between cavities were damaged too, due to strong vibration [1].

Acceleration cavities, such as an RFQ, a DTL and an SDDL, were checked through visual inspection, vacuum test, and measurement of resonant frequencies and Q factors. As a result, small vacuum leaks at some flanges but



Figure 2: Flooding in the linac tunnel.

[#]hasegawa.kazuo@jaea.go.jp

no RF property changes were found. Displacement of the drift tubes in the DTL and SDTL cavities was observed by an alignment telescope. The measurement showed that a few drift tubes in the first DTL tank had approximately 0.1 mm displacement.

Damages on the building were more serious. Pillars in the room called “klystron gallery” inclined, because their bases were damaged. As a result, most of the cranes have not been available yet. In addition, air conditioning ducts and plumbing system were also severely damaged. Restoration on the building is underway.

Levelling and horizontal floor surveys were carried out to examine displacement of the tunnel floor [2]. It appeared that there was the deformation of several tens of millimetres in horizontal and vertical directions. It is time-consuming work to move the DTLs by several centimeters because a large number of heavy cables for electromagnets are connected. We considered a better scenario for the realignment of the DTLs and also the SDTLs to meet the entire restoration schedule with minimizing an effect on the beam degradation [3]. The realignment work is presently underway based on the scenario.

STATUS OF RCS

The RCS building is located approximately 400 m from the shore and 15 m above the sea level. The accelerator components are installed on the basement second floor of a main tunnel, and there is a sub-tunnel where power supply cables and cooling water pipes are installed. We have many high power devices, such as chilling refrigerators, cooling towers, capacitors, transformers, rectifiers, power distribution boards, etc., in the yard.

Since the yard subsided by 30 cm to 1 m at many places, high voltage distribution boards inclined very badly, and the bus bars for transmission were also damaged. Power supply should be cut off until the completion of these repairs.

The accelerator components in the yard suffered from serious damages. Many bases for capacitors and transformers for resonant power supplies and rectifiers for RF cavities inclined. There were many hollow spaces



Figure 3: Hollow space underneath of a base for capacitor and transformer racks in the RCS yard.

underneath of bases as shown in Fig. 3. Cable trays installed along the building and all 4 cooling towers for the water system were also damaged.

We evaluated damages on accelerator components with the following two steps. Firstly, we carried out a visual inspection of the components. Secondly, we carried out a low-power inspection of vacuum pumping system and diagnostic devices, etc. Our biggest concern is a status of ceramic chambers. We visually inspected them from the outside, and then conducted a vacuum test with using six turbo molecular pumps. The vacuum pressure dropped to an order of 10^{-4} – 10^{-5} Pa after four hours exhaust, indicating that there were no large leaks in the chambers and they were almost sound. In addition, we tested power supplies and monitors with using a low electric voltage. Although there were some minor malfunctions, no serious damages existed. In order to restore the yard and the high voltage electric boards, we have had complete power outage from the middle of June to the end of August. After having the electricity in September, we will start the restoration of the cooling water system, and will perform the detailed check of the components with using a high electric voltage.

STATUS OF MR

The MR facility consists of a main tunnel at the circumference of 1.6 km, two carry-in buildings, three power supply buildings, and three machine buildings for the HVAC and cooling water system, etc.

More than 30 cracks were found in the MR main tunnel, and groundwater leaked from these parts. Since the lighting in the tunnel restored on March 25 two weeks after the earthquake, we could investigate the status of MR, finding that some electromagnets were continuously hit by leaked groundwater as in Fig. 4. Fortunately, the tunnels, except a part of the sub-tunnel, did not flood because of the presence of a side ditch. We carried out emergency sealing work at the points of heavy water leaks. An attached building to the main tunnel subsided, and a level difference was approximately 5 cm at the expansion joint part.

The beam line components were also tested, and vacuum pressure increased to 230 Pa within two weeks



Figure 4: Groundwater leakage in the MR tunnel. The magnet is covered with the sheet.

after the pump stopped due to earthquake. This pressure was approximately three orders of magnitude higher than that at normal stop. There was a relatively large leak at 10^{-4} Pa·m³/sec in a flange joint of the septum electromagnet. After the restoration of the control computer, we examined the pressure history, confirming that this leak occurred at the earthquake. We had a detailed test all over the ring, and fortunately, there were no leaks in the beam ducts. As for the MR, the damage of the infrastructure was relatively lighter than those of the linac and the RCS, incoming panels/lines for high receiving voltages, air conditioning system, and cooling water system had been restored by the end of May. With the test of the main electromagnet power supply on May 30 as a starter, we have tested in operation mode of electromagnets in the beam transport line, steering magnets, devices for slow extraction, an RF acceleration system, injection devices, and fast extraction devices, sequentially. It was confirmed that there were no serious problems. A malfunction such as interlamellar short circuits was not recognized even for the electromagnet which got wet with groundwater drops. Inspection of the various beam monitor system has been continued, and no serious damage has been found to date.

Inspection of main electromagnets was performed with using a laser tracker from April 18 through May 30 [4]. It appeared that there was big displacement in some places as it was concerned. Displacement was horizontally ± 10 and vertically ± 15 mm. We are considering an effective way to align magnets.

STATUS OF EXPERIMENTAL FACILITIES

Regarding the MLF, an attached building for a long baseline of the neutron spectrometer sank approximately 15 cm compared to the main MLF building and damages were found on the beam line. Furthermore, a platform for the mercury target for the neutron production moved, and the connected bellows was lengthened. We need to replace the target, but the delivery is expected to be in November because the factory of the target vessel also suffered from the earthquake. Vacuum leak was found in half of the neutron shutters. In addition, most of the steel shielding blocks slipped off. The work of draw out and reload of several thousand tons of shielding blocks has been underway since June.

There were many subsidence spots around the building of Neutrino Experimental Facility. The restoration work has been carried out. On the other hand, very little damage was found in the main components up to date. Foreign researchers of the T2K group who went back

to their home countries gradually have come back to J-PARC since the middle of May.

Subsidence also occurred around the Hadron Experimental Facility. All 6 bolts to fix the north and south beam direction were broken, and it appeared that there was a danger of collapse. The restoration work has been completed by the end of August. A big damage was not found in the main components, but there are many gaps between shielding blocks. We plan to reload these blocks.

BEAM RESTORATION PLAN

On May 20, the J-PARC Center announced the restoration schedule [5]. The main points are as follows:

- We would start test operation with using beams in December of 2011.
- The user program will start with beam time of about 50 days until the end of March 2012 (within Japanese fiscal year of 2011).

Note that this schedule would be valid assuming the requested budget is usable as we plan. The schedule is also strongly influenced by a progress in infrastructural recovery particularly for the linac and the RCS.

J-PARC had delivered beams progressively since 2008. The accelerators ramped up the beam power, and delivered beams of 145 kW and 220 kW to T2K neutrino experiment and MLF, respectively, before the earthquake [6, 7]. The T2K group announced on June 15 that they first had detected 6 possible events which suggested the transformation from muon neutrinos to electron neutrinos based on the data collected before March 11, 2011 [8]. As remarkable results have been presented by researchers of the MLF and the Hadron Experimental Facility, effects from the suspension of experiments due to the earthquake are immense. We, however, are making the best effort to resume the beam operation as we planned.

REFERENCES

- [1] A. Miura, et al., in these proceedings, WEPC144.
- [2] T. Morishita, et al., in these proceedings, WEPS049.
- [3] M. Ikegami, et al., in these proceedings, MOOCB01.
- [4] M. Shirakata, et al., in these proceedings, TUPS057.
- [5] http://www.j-parc.jp/en/topics/2011/en.html#Recovery_schedule
- [6] H. Hotchi, in these proceedings, MOXBA01.
- [7] T. Koseki, in these proceedings, WEPS008.
- [8] http://www.kek.jp/intra-e/press/2011/J-PARC_T2Kneutrino.html